Forest Service Manti-La Sal National Forest opete Ranger District 540 North Main Street Ephraim, UT 84627 Phone # (435) 283-4151

Fax # (435) 283-5616

m 1023/023

File Code: 2800

Date: November 13, 2003

Tony Christofferson Property/Environmental Manager H.E. Davis Construction Inc. 525 West Arrowhead Trail Spanish Fork, UT 84639

Dear Mr. Christofferson:

A follow-up inspection to the letter dated November 12, 2003 was conducted of Henry Gypsum Mine on November 13, 2003. We thank you for your prompt response in removing the large diesel tank and contaminated soil from the site well before the deadline of December 1, 2003. The site clean up is adequate and therefore no further inspection is needed for this problem.

In addition, the reclamation of the truck turn-around is adequate and no other work needs to be performed on it.

Thank you for your cooperation in these matters.

Sincerely,

THOMAS H. SHORE

District Ranger

NOV 1 9 2003
DIV. OF OIL, GAS & MINING



